Silicon Power

SSD Firmware Update Software

Supported Operating Systems

Supported on XP SP3 Vista SP2 Win 7 and Fedora Core 14 / 32-bit.

Note:

- 1. Microsoft AHCI driver is required and Microsoft AHCI mode must be enabled on your computer.
- 2. You must have Administrator privileges on your computer to run this utility.
- 3. If update failed, please help try to demount the IRST mode.

Before Use

- 1. Updating your device may result in data loss. Therefore, we strongly recommend you back up your data before proceeding.
- 2. Please DO NOT unplug the device or the power source during firmware update. This may cause unpredictable damage.
- 3. Use only native SATA ports to perform upgrade. Do NOT use third party controllers.

Getting Started

1. Connect the Silicon-Power SSD to your PC or laptop. (To be used SATA interface directly. Do not used USB HUB)



2. Unzip the

file that is downloaded from SP website.



SSD firmware update software SP Recovery Utility

3. Double click

icon and open "SSD firmware update software".

4. SSD firmware update software will automatically scan for all devices.

5. Pop up corresponding firmware update program after download finished.



6. SSD firmware update program will automatically scan for all devices and list them in the main window.

110	Field Op	ualei			
	Model SPCC SSD110	Serial No. 000000014	FW Rev. 502ABBF0	Signature 190-0-22900	Capacity (GB) 223.57

7. Select one or more desired drives to update. If two or more drives need to be updated at the same time, please ensure that the last five digits of each selected drive in the Signature column are identical to each other or the update will fail.

Ø	F_FieldU	pdater v1			-		
		Field	Upd	ater		LS	SandForce DRIVEN. By LSI
A	.1	Model		Serial No.	FW Rev. Sig	gnature	Capacity (GB)
	0	SPCC SSD110		000000014	502ABBF0 190	0-0 22900	223.57
D	etected	Drives	Notam Blazas put a	check mark to the drives	that you want u	ndata. Click on drive icon to con th	a output from the last
op	eration.	onted unives detected on your s	ystem. Flease put a	check mark to the unives	ulat you wallt u	puble. Click on unvencon to see th	e output from the last
	Update I	Firmware Rescan For D	rives				About Exit

8. Check the box next to the desired drive(s) and click "Update firmware..."

SF_	FieldU	pdater v1			-		
1	5	Fiel	d Upd	ater			
A11		Model		Serial No.	FW Rev.	Signature	Capacity (GB)
		SPCC SSD110		000000014	502ABBF0	190-0-22900	223.57
List	of supp ation.	Drives orted drives detected	on your system. Please put a	a check mark to the drives	that you wa	nt update. Click on dri	ve icon to see the output from the last
	Update I	Firmware R	escan For Drives				About Exit

9. Select the corresponding firmware file (*.VIC), as indicated below, and click Open. (The below data is for reference)

Select Firmware File			×
S82ABBF0	► SSDFW2 ► 240GB	Search 240GB	م
Organize 🔻 New folde	r		= • 🔳 🔞
☆ Favorites	Name	Date modified	Туре
E Desktop	22306_SPCC_FW600_240GB.vic	2015/1/6 下午 02:32	VIC File
\rm Downloads	22677_SPCC_FW600_240GB.vic	2015/1/6 下午 02:32	VIC File
🗐 Recent Places	22789_SPCC_FW600_240GB.vic	2015/1/6 下午 02:32	VIC File
=	22881_SPCC_FW600_240GB.vic	2015/1/6 下午 02:32	VIC File
🥽 Libraries	22900_SPCC_FW600_240GB.vic	2015/1/6 下午 02:32	VIC File
Documents	22980_SPCC_PW600_240GB.vic	2015/1/6 下午 02:32	VIC File
🌙 Music	27410_SPCC_FW600_240GB.vic	2015/1/6下午02:32	VIC File
Pictures	27488_SPCC_FW600_200GB.vic	2015/1/6 下午 02:32	VIC File
Videos	27751_SPCC_FW600_240G2 vic	2015/1/6 下午 02:32	VIC File
	27756_SPCC_FW600_240GB.vit	2015/1/6 下午 02:32	VIC File
🖳 Computer	29540_SPCC_FW600_240GB.vic	2015/1/6 下午 02:32	VIC File
🏭 Local Disk (C:)	33009_SPCC_FW600_240GB.vic	2015/1/6 下午 02:32	VIC File 👻
👝 New Volume (D:) 🔻	•		P.
File <u>n</u> a	ame: 22900_SPCC_FW600_240GB.vic	Supported files	(*.vic *.FFP) 🔹
		Open	Cancel

10. A warning message window will pop up. Please ensure that all of your data stored on the drive(s) is backed up and then select "Proceed" to continue the update process. Click "Cancel" to exit the utility and back up your data if you have not already done so.

🔛 Warning 📃				
<u> </u>	Automatic restart may occur after this operation. You should save all unsaved data before proceeding. If you wish to cancel the operation and save unsaved data now, click Cancel, otherwise click Proceed.			
	Proceed Cancel			

11. Once the update has completed successfully, a green check mark will appear on the disk icon.

9	SF_Fi	eldU	odater v1		-		
		5 1 (Field Upd	later		LS	SandForce DRIVEN By LSI
	A11		Model	Serial No.	FW Rev.	Signature	Capacity (GB)
	V	\checkmark	SPCC SSD110	000000014	502ABBF0	190-0-22900	223.57
	Deteo	cted	Drives				
	List of operat	supp tion.	orted drives detected on your system. Please put a	a check mark to the drives	that you wa	nt update. Click on drive icon to see th	About From the last
	U	paate I	minwate Rescal FOI Drives				Hoodi EXII

12. Click "Rescan for Drives" to confirm that the SSD firmware has been updated successfully.

SF_FieldUpdater v1			
Field Upd	ater		
All Model	Serial No.	FW Rev. Signature	Capacity (GB)
E SPCC SSD110	000000014	505ABBF0 190-0-22900	223.57
Detected Drives			
List of supported drives detected on your system. Please put a operation.	check mark to the drives	that you want update. Click on dr	ive icon to see the output from the last
Update Firmware Rescan For Drives			About Exit

13. SSD firmware update program will automatically scan for all devices and list them in the main window.



14. Click left side "Firmware Upgrade", then clock right side "Firmware Upgrade"



15. Once the update has completed successfully, a "Upgrade Firmware Success!!" message window will pop up.



16. SSD firmware update program will automatically scan for all devices and list them in the main window.



17. Click left side "Firmware Upgrade", then clock right side "Firmware Upgrade"



18. Once the update has completed successfully, a "Upgrade Firmware Success!!" message window will pop up.

