

Silicon Power PHD 3.0 Diamond D03 Firmware Update

Date : 2014/09/30


※Please launch this Firmware Update AP on USB 2.0 Host port※

※Use Bridge Controller to update the Firmware※




(Pic1.)

Launch Silicon-Power_3609_FWUpdaterv3.00A01.exe as the example of Pic 1.




(Pic 2)

Please click “(Pic1)Update” , the application will try to detect the Device (Pic 2)



(Pic 3)

It will be processed Firmware Update automatically when the application detect the device (Pic 3)



(Pic 4)

Firmware Update process completely (Pic 4)



(Pic 5)

Please kindly be noted that you will get this warn message if you try to update the FW on USB 3.0 port. (Pic 5)

* Please be sure to switch to standard USB 2.0 port when you try to update Firmware.